



December 13, 2022

Ms. Maureen Hatfield, P.G.

Texas Commission on Environmental Quality

MC-127

VCP-CA Section, Team 1, Remediation Division

P.O. Box 13087

Austin, Texas 78711-3087

**RE: WEEKLY STATUS UPDATE – ENGLEWOOD YARD NORTH BYPASS PROJECT
UNION PACIFIC RAILROAD HOUSTON WOOD PRESERVING WORKS SITE
4910 LIBERTY ROAD FACILITY, HOUSTON, TEXAS
POST-CLOSURE CARE PERMIT NO. 50343, INDUSTRIAL SWR NO. 31547**

Dear Ms. Hatfield:

Golder Associates USA Inc., a member of WSP, (WSP Golder) on behalf of Union Pacific Railroad (UPRR), prepared this weekly status update for the Englewood Yard North By-Pass Project (the Project) that includes areas of construction within the UPRR Houston Wood Preserving Works (HWPW) site (the Site) (Post-Closure Care Permit No. 50343) located at 4910 Liberty Road, Houston, Texas. Below is a summary of the Project activities conducted at the Site for the reporting period:

Week Period: *December 5 through December 11, 2022*

Construction activities performed during this reporting period did not involve excavation of soils within the HWPW Site.

Dust Control and Air Monitoring

Since no soil excavation activities were performed during this reporting period within the Site, Dust Control and Air Monitoring was not conducted during this reporting period.

Soil Management

No soil excavation activities were performed during this reporting period within the Site.

Stormwater Management

There was no rainfall during this reporting period that resulted in management of stormwater within the site.

Planned Construction Activities for the period between **December 12 and December 18, 2022:**

Per the UPRR schedule, the planned activities include the installation of a new track in the Rail Ballast Cap adjacent to the south of the Asphalt Road Cap. Track installation is planned to occur on December 13, 2022.

Dust Control and Air Monitoring

Air monitoring per the approved Air Monitoring Plan (July 8, 2021) will continue to be conducted for the duration of the track installation activities in the Rail Ballast Cap.

Soil Management

Soils will not be generated during the planned activities for the week period of December 12 through December 18, 2022.

If you have any questions or need additional information, please feel free to contact Mr. Kevin Peterburs of UPRR at (414) 267-4164.

Sincerely,

Golder Associates Inc.



Anthony Reid
Sr. Consultant Geologist



Eric Matzner
Practice Leader/ Principal