Bryan W. Shaw, Ph.D., P.E., Chairman Toby Baker, Commissioner Jon Niermann, Commissioner Richard A. Hyde, P.E., Executive Director



## TEXAS COMMISSION ON ENVIRONMENTAL QUALITY

Protecting Texas by Reducing and Preventing Pollution
June 27, 2017

Mr. Geoffrey Reeder, P.G. Manager Environmental Site Remediation Safety Union Pacific Railroad 24125 Aldine Westfield Road Spring, TX 77373

Re:

Approval with Comment

DNAPL Recovery Activities Report, dated March 31, 2017

Union Pacific Railroad Houston Wood Preserving Works Facility, 4910 Liberty Rd.,

Houston, Harris County, TX,

TCEQ SWR No. 31547; TCEQ Permit/Compliance Plan No. 50343;

EPA ID No.TXD000820266

Customer No. CN600131098; Regulated Entity No. RN100674613

## Dear Mr. Reeder:

The Texas Commission on Environmental Quality (TCEQ) has reviewed the above referenced report received by the Remediation Division on March 31, 2017. The report documents the monitoring of DNAPL thickneses and DNAPL recovery efforts that are being implemented at MW-57A, MW-78A, MW-12B, MW-32B, MW-41B, MW-57B, MW-70B, MW-75B, MW-23C, MW-34C/MW34CR, MW-44C, MW45C, and MW-46C to remove readily recoverable DNAPL from the wells as well as reducing DNAPL thicknesess. Please continue with DNAPL recovery efforts and reporting results as proposed in the above referenced actitities report.

An original and one copy on CD of future reports should be submitted to the Remediation Division at the letterhead address using Mail Code MC-127. An additional copy should be submitted to the TCEQ Region Office.Questions concerning this letter should be directed to me at (512) 239-2034 or maureen.hatfield@tceq.texas.gov. Thank you for your cooperation in this matter.

Sincerely.

Maureen Hatfield, P.G., Project Manager

James Alexandeld

Team 1, VCP-CA Section, MC127

Remediation Division

MH/bk

cc: Mr. Jason Ybarra, Waste Section Manager, TCEQ Region 12 Office, Houston